

Cross Reference

The following table represents a cross reference guide for all Analog devices that are manufactured by Motorola. Where the Motorola part number differs from the industry part

number, the Motorola device is a “form, fit and function” replacement for the industry part number. However, some differences in characteristics and/or specifications may exist.

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
75175	SN75175		94, 95
9640PC	MC26S10P#		94
9667PC	MC1413P		96
9668PC	MC1416P		96
AD589J		LM385Z-1.2	83
AD589K		LM385Z-1.2	83
AD589L		LM385Z-1.2	83
AD589M		LM385BZ-1.2	83
AM201AD		LM201AN	21
AM201D		LM201AN	21
AM26LS30P	AM26LS30PC		95
AM26LS31CJ	AM26LS31PC#		94
AM26LS31CN	AM26LS31PC#		94
AM26LS32ACJ	AM26LS32D#		94
AM26LS32ACN	AM26LS32PC#		94
AM26LS32PC	AM26LS32PC#		94
AM723PC	MC1723CP		32
AN5150		MC34129P	39, 114, 130, 135
CA081AE		TL081ACP	21
CA081E		TL081CP	21
CA082AE		TL082ACP	22
CA082E		TL082CP	22
CA084AE		TL084ACN	23
CA084E		TL084CN	23
CA1391E	MC1391P		144
CA1458S	MC1458CP1		22
CA239AE	LM239AN		26
CA239E	LM239N		26
CA3045F		MC3346P	146
CA3046	MC3346P		146
CA3058		CA3059	71
CA3059	CA3059		71
CA3079	CA3079		71
CA3086F		MC3346P	146
CA3136A		MC3346P	146
CA3146		MC3346P	146
CA339AE	LM339AN		26
CA339E	LM339N		26
CA723CE	MC1723CP		32
CA741CS	MC1741CP1		21
CS2842AD	UC2842BD1		40
CS2843AD	UC2843BD1		40
CS2844D	UC2844BD1		40
CS2845D	UC2845BD1		40
CS3842AD	UC3842BD1		39
CS3843AD	UC3843BD1		40

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
CS3844D	UC3844BD1		40
CS3845D	UC3845BD1		40
DM8822N		MC1489AP	94
DS1233M		MC34064P-5	57
DS1488N	MC1488P		95
DS1489AN	MC1489AP		94
DS1489N	MC1489P		94
DS26LS32N	AM26LS32P#		94
DS26S10CN	MC26S10P#		94
DS3650N	MC3450P#		94
ICL741CLNPA		MC1741CP1	21
ICL741CLNTY		MC1741CP1	21
ICL8008CPA		LM301AN	21
ICL8008CTY		LM301AN	21
ICL8017CTW		LM301AN	21
ICL8017MTW		LM301AN	21
ICL8069CCZR		LM385BZ-1.2	83
ICL8069DCZR		LM385BZ-1.2	83
IP33063N	MC33063AP1		41
IP34060AN	MC34060AP		39
IP34063N	MC34063AP1		41
IP3525AN	SG3525AN		42
IP3526N	SG3526N		42
IP3527AN	SG3527AN		42
IP494ACJ		TL594IN	42
IP494ACN		TL594CN	42
IR3M03A		MC34063AP1	41
IR3M03AN		MC34063AD	41
ITT3710		MC1391P	144
ITT656	MC1413P		96
L144AP		LM324N	23
L203	MC1413P		96
L387		MC33267T	29, 30, 35, 36, 169
LF347BN	LF347BN		23
LF347N	LF347N		23
LF351BN		MC34001BP	21
LF351N	LF351N		21
LF353AN	MC34002AP		22
LF353BN	MC34002BP		22
LF353D	LF353D		22
LF353N	LF353N		22
LF411CD	LF411CD		21
LF412CD	LF412CD		22
LF441CD	LF441CD		21
LF441CN	LF441CN		21
LF442CD	LF442CD		22
LF442CN	LF442CN		22
LF444CD	LF444CD		23
LF444CN	LF444CN		23
LM11CLN	LM11CLN		21
LM11CN	LM11CN		21
LM139N	MC1391P		144

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
LM1489AN	MC1489AP		94
LM1489N	MC1489P		94
LM1496M	MC1496D		103
LM1496N	MC1496P		103
LM1889		MC1374P	145, 158
LM1981		MC13020P	143
LM201AD	LM201AD		21
LM201AN	LM201AN		21
LM201AP		LM201AN	21
LM211D	LM211D		26
LM211M	LM211D		26
LM224D	LM224D		23
LM224M	LM224D		23
LM224N	LM224N		23
LM239AN	LM239AN		26
LM239D	LM239D		26
LM239M	LM239D		26
LM239N	LM239N		26
LM240LAZ-5.0		MC78L05ACP	29
LM240LAZ-6.0		MC78L05ACP	29
LM240LAZ-8.0		MC78L08ACP	29
LM240LAZ-12		MC78L12ACP	29
LM240LAZ-15		MC78L15ACP	29
LM240LAZ-18		MC78L18ACP	29
LM240LAZ-24		MC78L24ACP	29
LM249N		MC4741CP	23
LM2575	LM2575		41
LM258D	LM258D		22
LM258M	LM258D		22
LM258N	LM258N		22
LM285Z-1.2	LM285Z-1.2		83
LM285Z-2.5	LM285Z-2.5		83
LM2901D	LM2901D		26
LM2901M	LM2901D		26
LM2901N	LM2901N		26
LM2902D	LM2902D		24
LM2902M	LM2902D		24
LM2902N	LM2902N		24
LM2903D	LM2903D		26
LM2903M	LM2903D		26
LM2903N	LM2903N		26
LM2903P	LM2903N		26
LM2904M	LM2904D		23
LM2904N	LM2904N		23
LM2905N		MC1455P1	183
LM2931AD-5.0	LM2931AD-5.0		29, 30
LM2931AT-5.0	LM2931AT-5.0		29, 30
LM2931AZ-5.0	LM2931AZ-5.0		29, 30
LM2931CD	LM2931CD		31, 169
LM2931CM	LM2931CD		31, 169
LM2931CT	LM2931CT		31, 169

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
LM2931D-5.0	LM2931D-5.0		29, 30
LM2931D	LM2931D-5.0		29, 30
LM2931T-5.0	LM2931T-5.0		29, 30
LM2931Z-5.0	LM2931Z-5.0		29, 30
LM2935T	LM2935T		30, 169
LM293D	LM293D		26
LM301AD	LM301AD		21
LM301AM	LM301AD		21
LM301AN	LM301AN		21
LM301AP		LM301AN	21
LM3045		MC3346P	146
LM3046N	MC3346P		146
LM308AD	LM308AD		21
LM308AN	LM308AN		21
LM308P		MC3356P	101
LM311D	LM311D		26
LM311M	LM311D		26
LM311N	LM311N		26
LM311P	LM311N		26
LM3146A		MC3346P	146
LM3146		MC3346P	146
LM317KC	LM317T		32
LM317KD		LM317T	32
LM317LD	LM317LD		31
LM317LZ	LM317LZ		31
LM317MP		LM317MT	32
LM317P		LM317T	32
LM317T	LM317T		32
LM3189		MC3356P	101
LM320LZ-12		MC79L12ACP	29
LM320LZ-15		MC79L15ACP	29
LM320LZ-5.0		MC79L05ACP	29
LM320MP-5.0		MC7905CT	30
LM320MP-5.2		MC7905.2CT	30
LM320MP-6.0		MC7906CT	30
LM320MP-8.0		MC7908CT	30
LM320MP-12		MC7912CT	30
LM320MP-15		MC7915CT	30
LM320MP-18		MC7918CT	30
LM320MP-24		MC7924CT	30
LM320T-12		MC7912CT	30
LM320T-15		MC7915CT	30
LM320T-5.0		MC7905CT	30
LM320T-5.2		MC7905.2CT	30
LM322N		MC1455P1	183
LM323AT	LM323AT		30
LM323T	LM323T		30
LM324AD	LM324AD		23
LM324AN	LM324AN		23
LM324D	LM324D		23
LM324M	LM324D		23
LM324N	LM324N		23

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
LM337MP		LM337MT	32
LM337MT	LM337MT		32
LM337T	LM337T		32
LM339AD	LM339AD		26
LM339AM	LM339AD		26
LM339AN	LM339AN		26
LM339D	LM339D		26
LM339N	LM339N		26
LM339P		LM339N	26
LM340AT-12	LM340AT-12		30
LM340AT-15	LM340AT-15		30
LM340AT-5.0	LM340AT-5.0		30
LM340KC-12	LM340T-12		30
LM340KC-15	LM340T-15		30
LM340LAZ-5.0		MC78L05ACP	29
LM340LAZ-8.0		MC78L08ACP	29
LM340LAZ-12		MC78L12ACP	29
LM340LAZ-18		MC78L18ACP	29
LM340LAZ-24		MC78L24ACP	29
LM340T-5.0	LM340T-5.0		30
LM340T-6.0	LM340T-6.0		30
LM340T-8.0	LM340T-8.0		30
LM340T-12	LM340T-12		30
LM340T-15	LM340T-15		30
LM340T-18	LM340T-18		30
LM340T-24	LM340T-24		30
LM341P-12		MC78M12CT	29
LM341P-15		MC78M15CT	29
LM341P-18		MC78M18CT	29
LM341P-24		MC78M24CT	29
LM341P-5.0		MC78M05CT	29
LM341P-6.0		MC78M06CT	29
LM341P-8.0		MC78M08CT	29
LM342P-12		MC78M12CT	29
LM342P-15		MC78M15CT	29
LM342P-18		MC78M18CT	29
LM342P-24		MC78M24CT	29
LM342P-5.0		MC78M05CT	29
LM342P-6.0		MC78M06CT	29
LM342P-8.0		MC78M08CT	29
LM348D	LM348D		23
LM348M	LM348D		23
LM349N		MC4741CP	23
LM350T	LM350T		32
LM358AN		LM358N	22
LM358D	LM358D		22
LM358N	LM358N		22
LM363AN		MC3450P#	94
LM363N		MC3450P#	94
LM385BZ-1.2	LM385BZ-1.2		83
LM385BZ-2.5	LM385BZ-2.5		83
LM385D-1.2	LM385D-1.2		83

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
LM385D-2.5	LM385D-2.5		83
LM385M-1.2	LM385D-1.2		83
LM385M-2.5	LM385D-2.5		83
LM385Z-1.2	LM385Z-1.2		83
LM385Z-2.5	LM385Z-2.5		83
LM386N		MC34119P	125, 126, 127, 129, 130, 135, 136, 143
LM3905N		MC1455P1	183
LM393AN	LM393AN		26
LM393D	LM393D		26
LM393JG		LM393N	26
LM393M	LM393D		26
LM393N	LM393N		26
LM431ACZ	TL431ACLP		83
LM431ACM	TL431ACD		83
LM4250CN		MC1776CP1	21
LM555CN	MC1455P1		183
LM556CN	MC3456P		183
LM703LN		MC1350P	24, 144
LM723CN	MC1723CP		32
LM741EN		MC1741CP1	21
LM7805CT	MC7805CT		30
LM7812CT	MC7812CT		30
LM7815CT	MC7815CT		30
LM78L05ACZ	MC78L05ACP		29
LM78L05CZ	MC78L05CP		29
LM78L08ACZ	MC78L08ACP		29
LM78L08CZ	MC78L08CP		29
LM78L12ACZ	MC78L12ACP		29
LM78L12CZ	MC78L12CP		29
LM78L15ACZ	MC78L15ACP		29
LM78L15CZ	MC78L15CP		29
LM78L18ACZ	MC78L18ACP		29
LM78L18CZ	MC78L18CP		29
LM78L24ACZ	MC78L24ACP		29
LM78L24CZ	MC78L24CP		29
LM78M05CP		MC78M05CT	29
LM78M06CP		MC78M06CT	29
LM78M12CP		MC78M12CT	29
LM78M15CP		MC78M15CT	29
LM7905CT	MC7905CT		30
LM7912CT	MC7912CT		30
LM7915CT	MC7915CT		30
LM79L05ACZ	MC79L05ACP		29
LM79L12ACZ	MC79L12ACP		29
LM79L15ACZ	MC78L15ACP		29
LM79M05CP		MC79M05CT	29
LM79M12CP		MC79M12CT	29
LM79M15CP		MC79M15CT	29
LM833D	LM833D		22
LM833N	LM833N		22
LM833P	LM833N		22

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
LM837N		MC33079P	24
LMC6482D		MC33202D	23
LMC6482P		MC33202P	23
LMC6484D		MC33204D	24
LMC6484P		MC33204P	24
LP2950CZ-3.0	LP2950CZ-3.0		29, 30
LP2950CZ-3.3	LP2950CZ-3.3		29, 30
LP2950CZ-5.0	LP2950CZ-5.0		29, 30
LP2950ACZ-3.0	LP2950ACZ-3.0		29, 30
LP2950ACZ-3.3	LP2950ACZ-3.3		29, 30
LP2950ACZ-5.0	LP2950ACZ-5.0		29, 30
LP2951CM	LP2951CD		31
LP2951ACM	LP2951ACD		31
LP2951CM-3.0	LP2951CD-3.0		31
LP2951CM-3.3	LP2951CD-3.3		31
LP2951ACM-3.0	LP2951ACD-3.0		31
LP2951ACM-3.3	LP2951ACD-3.3		31
LP2951CN	LP2951CN		31
LP2951ACN	LP2951ACN		31
LP2951CN-3.0	LP2951CN-3.0		31
LP2951CN-3.3	LP2951CN-3.3		31
LP2951ACN-3.0	LP2951ACN-3.0		31
LP2951ACN-3.3	LP2951ACN-3.3		31
LT1083		MC34268DT	29, 30, 38
LT1431CZ	TL431BCLP		83
LTC699CN8		MC34064D-5	57
LTC699IN8		MC33064D-5	57
MAX809LCPA		MC34064P-5	57
MB3759	TL494CN		42
N5558V	MC1458P1		22
N5723A		MC1723CP	32
N5741A		MC1741CP1	21
N5741V	MC1741CP1		21
NE550A		MC1723CP	32
NE555D	MC1455D		183
NE555V	MC1455P1		183
NE556D	NE556D		183
NE5561N		MC34060AP	39
NE5234D		MC33204D	24
NE5234P		MC33204P	24
OP-01P		MC1436P1	21
RC1458DN	MC1458P1		22
RC4136DP		MC3403P	23
RC4136N		MC3403P	23
RC4558DN	MC4558CP1		22
RC4558P	MC4558CP1		22
RC723DB	MC1723CP		32
RC741DN	MC1741CP1		21
RE5VL47A	MC34164P-5		57
RH5RE30AA-T1	MC78LC30HT1		32
RH5RE33AA-T1	MC78LC33HT1		32
RH5RE40AA-T1	MC78LC40HT1		32

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
RH5RE50AA-T1	MC78LC50HT1		32
RN5RG30AA-TR	MC78BC30NTR		33
RN5RG33AA-TR	MC78BC33NTR		33
RN5RG40AA-TR	MC78BC40NTR		33
RN5RG50AA-TR	MC78BC50NTR		33
RH5RH301A-T1	MC33466H-30JT1		44
RH5RH302B-T1	MC33466H-30LT1		44
RH5RH331A-T1	MC33466H-33JT1		44
RH5RH332B-T1	MC33466H-33LT1		44
RH5RH501A-T1	MC33466H-50JT1		44
RH5RH502B-T1	MC33466H-50LT1		44
RH5RI301B-T1	MC33463H-30KT1		43
RH5RI302B-T1	MC33463H-30LT1		43
RH5RI331B-T1	MC33463H-33KT1		43
RH5RI332B-T1	MC33463H-33LT1		43
RH5RI501B-T1	MC33463H-50KT1		43
RH5RI502B-T1	MC33463H-50LT1		43
RH5RL30AA-T1	MC78FC30HT1		33
RH5RL33AA-T1	MC78FC33HT1		33
RH5RL40AA-T1	MC78FC40HT1		33
RH5RL50AA-T1	MC78FC50HT1		33
RH5VT09AA-T1	MC33464H-09AT1		55
RH5VT20AA-T1	MC33464H-20AT1		55
RH5VT27AA-T1	MC33464H-27AT1		55
RH5VT30AA-T1	MC33464H-30AT1		55
RH5VT45AA-T1	MC33464H-45AT1		55
RH5VT09CA-T1	MC33464H-09CT1		55
RH5VT20CA-T1	MC33464H-20CT1		55
RH5VT27CA-T1	MC33464H-27CT1		55
RH5VT30CA-T1	MC33464H-30CT1		55
RH5VT45CA-T1	MC33464H-45CT1		55
RN5RL30AA-TR	MC78FC30NTR		33
RN5RL33AA-TR	MC78FC33NTR		33
RN5RL40AA-TR	MC78FC40NTR		33
RN5RL50AA-TR	MC78FC50NTR		33
RN5VD09AA-TR	MC33465N-09ATR		56
RN5VD20AA-TR	MC33465N-20ATR		56
RN5VD27AA-TR	MC33465N-27ATR		56
RN5VD30AA-TR	MC33465N-30ATR		56
RN5VD45AA-TR	MC33465N-45ATR		56
RN5VD09CA-TR	MC33465N-09CTR		56
RN5VD20CA-TR	MC33465N-20CTR		56
RN5VD27CA-TR	MC33465N-27CTR		56
RN5VD30CA-TR	MC33465N-30CTR		56
RN5VD45CA-TR	MC33465N-45CTR		56
RN5VT09AA-TR	MC33464N-09ATR		56
RN5VT20AA-TR	MC33464N-20ATR		56
RN5VT27AA-T4	MC33464N-27ATR		56
RN5VT30AA-TR	MC33464N-30ATR		56
RN5VT45AA-TR	MC33464N-45ATR		56
RN5VT09CA-TR	MC33464N-09CTR		56
RN5VT20CA-TR	MC33464N-20CTR		56

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
RN5VT27CA-TR	MC33464N-27CTR		56
RN5VT30CA-TR	MC33464N-30CTR		56
RN5VT45CA-TR	MC33464N-45CTR		56
S-80743AN		MC34164P-3	57
SA555N	MC1455BP1		183
SAA1042		SAA1042V	78
SG1458M	MC1458P1		22
SG1496N	MC1496P		103
SG1596J	MC1496BP		103
SG201AM	LM201AN		21
SG201AN		LM201AN	21
SG201M	LM201AN		21
SG201N		LM201AN	21
SG224N	LM224N		23
SG300N		MC1723CP	32
SG301AM	LM301AN		21
SG301AN		LM301AN	21
SG308AM	LM308AN		21
SG3118AM		LM308AN	21
SG311M	LM311N		26
SG317P	LM317T		32
SG317R		LM317T	32
SG324N	LM324N		23
SG337P	LM337T		32
SG337R		LM337T	32
SG3423M		MC3423P1	54
SG3525AN	SG3525AN		42
SG3526N	SG3526N		42
SG3527AN	SG3527AN		42
SG3561	MC34261P		51
SG4250CM		MC1776CP1	21
SG555CM	MC1455P1		183
SG556CN	MC3456P		183
SG723CN	MC1723CP		32
SG741CM	MC1741CP1		21
SG777CN		LM308AN	21
SG7805ACP	MC7805ACT		30
SG7805ACR		MC7805ACT	30
SG7805ACT		MC7805ACT	30
SG7805CP	MC7805CT		30
SG7806ACP	MC7806ACT		30
SG7806ACR		MC7806ACT	30
SG7806ACT		MC7806ACT	30
SG7806CP	MC7806CT		30
SG7806CR		MC7806CT	30
SG7808ACP	MC7808ACT		30
SG7808ACT		MC7808ACT	30
SG7808CP	MC7808CT		30
SG7808CR		MC7808CT	30
SG7812ACP	MC7812ACT		30
SG7812ACR		MC7812ACT	30
SG7812ACT		MC7812ACT	30

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
SG7812CP	MC7812CT		30
SG7812CR		MC7812CT	30
SG7815ACP	MC7815ACT		30
SG7815ACR		MC7815ACT	30
SG7815ACT		MC7815ACT	30
SG7815CP	MC7815CT		30
SG7815CR		MC7815CT	30
SG7815CT		MC7815CT	30
SG7818ACP	MC7818ACT		30
SG7818ACR		MC7818ACT	30
SG7818ACT		MC7818ACT	30
SG7818CP	MC7818CT		30
SG7818CR		MC7818CT	30
SG7824ACP	MC7824ACT		30
SG7824ACR		MC7824ACT	30
SG7824ACT		MC7824ACT	30
SG7824CP	MC7824CT		30
SG7824CR		MC7824CT	30
SG7905.2CP	MC7905.2CT		30
SG7905.2CR		MC7905.2CT	30
SG7905.2CT		MC7905.2CT	30
SG7905ACP	MC7905ACT		30
SG7905ACR		MC7905ACT	30
SG7905ACT		MC7905ACT	30
SG7905CP	MC7905CT		30
SG7905CR		MC7905CT	30
SG7905CT		MC7905CT	30
SG7908CP	MC7908CT		30
SG7908CR		MC7908CT	30
SG7908CT		MC7908CT	30
SG7912ACP	MC7912ACT		30
SG7912ACR		MC7912ACT	30
SG7912ACT		MC7912ACT	30
SG7912CP	MC7912CT		30
SG7912CR		MC7912CT	30
SG7912CT		MC7912CT	30
SG79015ACP	MC7915ACT		30
SG7915ACR		MC7915ACT	30
SG7915ACT		MC7915ACT	30
SG7915CP	MC7915CT		30
SG7915CR		MC7915CT	30
SG7915CT		MC7915CT	30
SG7918CP	MC7918CT		30
SN75LBC086		MC34055DW	90, 96
SN75150N		MC1488P	95
SN75154N		MC1489P	94
SN75174N	MC75174BP		94
SN75175N	SN75175N		94
SN75188N	MC1488P		95
SN75189AN	MC1489AP		94
SN75189N	MC1489P		94
SN75468N	MC1413P		96

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
SN76591P	MC1391P		144
SN76600P	MC1350P		24, 144
SSS201AP	LM201AN		21
SSS301AP	LM301AN		21
TA7504P	MC1741CP1		21
TA7506P	LM301AN		21
TA75071P		MC34001P	21
TA75072P		MC34002P	22
TA75074F		MC34004P	23
TA75339F	LM339D		26
TA75339P	LM339N		26
TA75358CF	LM358D		22
TA75358CP	LM358N		22
TA75393F	LM393D		26
TA75393P	LM393N		26
TA75458F	MC1458D		22
TA75458P	MC1458CP1		22
TA75558P	MC4558CP1		22
TA7555F	MC1455D		183
TA7555P	MC1455P1		183
TA75902F	LM324D		23
TA76494P		TL494IN	42
TA78005AP	MC7805CT		30
TA78006AP	MC7806CT		30
TA78008AP	MC7808CT		30
TA78012AP	MC7812CT		30
TA78015AP	MC7815CT		30
TA78018AP	MC7818CT		30
TA78024AP	MC7824CT		30
TA78L005AP		MC78L05ACP	29
TA78L008AP		MC78L08ACP	29
TA78L012AP		MC78L12ACP	29
TA78L015AP		MC78L15ACP	29
TA78L018AP		MC78L18ACP	29
TA78L024AP		MC78L24ACP	29
TA78M05P	MC78M05CT		29
TA78M06P	MC78M06CT		29
TA78M08P	MC78M08CT		29
TA78M12P	MC78M12CT		29
TA78M18P	MC78M18CT		29
TA78M20P	MC78M20CT		29
TA78M24P	MC78M24CT		29
TA79005P	MC7905CT		30
TA79006P	MC7906CT		30
TA79008P	MC7908CT		30
TA79012P	MC7912CT		30
TA79015P	MC7915CT		30
TA79018P	MC7918CT		30
TA79024P	MC7924CT		30
TA79L012P		MC79L12P	29
TA79L015P		MC79L15P	29
TA79L018P		MC79L18P	29

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
TA79L024P		MC79L24P	29
TB920		MC1391P	144
TBA920S		MC1391P	144
TCF5600	TCF5600		50
TD62003P/AP	MC1413P		96
TD62479P	MC1374P		145, 158
TDA1085C	TDA1085C		79
TDA1085		TDA1085C	79
TDA1185A	TDA1185A#		80
TDA4817		MC34261P	51
TDC1048		MC10319P	85
TK115	MC33264		34
TL022CP		LM358N	22
TL044CJ		LM324N	23
TL062ACP	TL062ACP		22
TL062CD	TL062CD		22
TL062CP	TL062CP		22
TL062VP	TL062VP		22
TL064ACD	TL064ACD		23
TL064ACN	TL064ACN		23
TL064CD	TL064CD		23
TL064CN	TL064CN		23
TL064VN	TL064VN		24
TL071ACD	TL071ACD		21
TL071ACP	TL071ACP		21
TL071CD	TL071CD		21
TL071CP	TL071CP		21
TL072ACD	TL072ACD		22
TL072ACP	TL072ACP		22
TL072CD	TL072CD		22
TL072CP	TL072CP		22
TL074ACN	TL074ACN		23
TL074CN	TL074CN		23
TL081ACD	TL081ACD		21
TL081ACP	TL081ACP		21
TL081CD	TL081CD		21
TL081CP	TL081CP		21
TL082ACP	TL082ACP		22
TL082CD	TL082CD		22
TL082CP	TL082CP		22
TL084ACN	TL084ACN		23
TL084CN	TL084CN		23
TL431CD	TL431CD		83
TL431CLP	TL431CLP		83
TL431CP	TL431CP		83
TL431ILP	TL431ILP		83
TL431IP	TL431IP		83
TL494CN	TL494CN		42
TL494IN	TL494IN		42
TL497CN		MC34063AP1	41
TL594CN	TL594CN		42
TL594IN	TL594IN		42

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
TL780-05CKC	TL780-05CKC		30
TL780-12CKC	TL780-12CKC		30
TL780-15CKC	TL780-15CKC		30
TL7805ACKC	MC7805ACT		30
TLC2272D		MC33202D	23
TLC2272P		MC33202P	23
TLC2274D		MC33204D	24
TLC2274P		MC33204P	24
μA1391PC	MC1391P		144
μA1458CP	MC1458CP1		22
μA1458CTC	MC1458CP1		22
μA1458P	MC1458P1		22
μA1458TC	MC1458P1		22
μA2240PC		MC1455P1	183
μA301AT	LM301AN		21
μA3045		MC3346P	146
μA3046DC	MC3346P		146
μA311T	LM311N		26
μA317UC	LM317T		32
μA3303P	MC3303P		23
μA3403P	MC3403P		23
μA4136PC		MC4741CP	23
μA431AWC	TL431CP		83
μA4558TC	MC4558CP1		22
μA494PC	TL494CN		42
μA555TC	MC1455P1		183
μA556PC	MC3456P		183
μA723CN	MC1723CP		32
μA723PC	MC1723CP		32
μA741CP	MC1741CP1		21
μA742DC		CA3059	71
μA757DC		MC1350P	24, 144
μA757DM		MC1350P	24, 144
μA775PC	LM339N		26
μA776TC	MC1776CP1		21
μA7805CKC	MC7805CT		30
μA7805UC	MC7805CT		30
μA7805UV	MC7805BT		30
μA7806CKC	MC7806CT		30
μA7806UC	MC7806CT		30
μA7806UV	MC7806BT		30
μA7808CKC	MC7808CT		30
μA7808UC	MC7808CT		30
μA7808UV	MC7808BT		30
μA7812CKC	MC7812CT		30
μA7812UC	MC7812CT		30
μA7812UV	MC7812BT		30
μA7815CKC	MC7815CT		30
μA7815UC	MC7815CT		30
μA7815UV	MC7815BT		30
μA7818CKC	MC7818CT		30
μA7818UC	MC7818CT		30

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
μA7818UV	MC7818BT		30
μA7824CKC	MC7824CT		30
μA7824UC	MC7824CT		30
μA7824UV	MC7824BT		30
μA78GU1C		LM317T	32
μA78GUC		LM317T	32
μA78L05ACLP	MC78L05ACP		29
μA78L05AWC		MC78L05ACP	29
μA78L08ACLP	MC78L08ACP		29
μA78L08AWC		MC78L08ACP	29
μA78L12ACLP	MC78L12ACP		29
μA78L12AWC		MC78L12ACP	29
μA78L15ACLP	MC78L15ACP		29
μA78L15AWC		MC78L15ACP	29
μA78L18AWC		MC78L18ACP	29
μA78L24AWC	MC78L24ACP		29
μA78M05CKC	MC78M05CT		29
μA78M05CKD		MC78M05CT	29
μA78M05UC	MC78M05CT		29
μA78M06CKC	MC78M06CT		29
μA78M06CKD		MC78M06CT	29
μA78M06UC	MC78M06CT		29
μA78M08CKC	MC78M08CT		29
μA78M08CKD		MC78M08CT	29
μA78M08UC	MC78M08CT		29
μA78M12CKC	MC78M12CT		29
μA78M12CKD		MC78M12CT	29
μA78M12UC	MC78M12CT		29
μA78M15CKC	MC78M15CT		29
μA78M15CKD		MC78M15CT	29
μA78M15UC	MC78M15CT		29
μA78M18UC	MC78M18CT		29
μA78M20CKC	MC78M20CT		29
μA78M20CKD		MC78M20CT	29
μA78M20UC	MC78M20CT		29
μA78M24CKC	MC78M24CT		29
μA78M24CKD		MC78M24CT	29
μA78M24UC	MC78M24CT		29
μA78MGT2C		LM317T	32
μA78MGU1C		LM317T	32
μA78MGUC		LM317MT	32
μA78S40PC	μA78S40PC		41
μA78S40PV	μA78S40PV		41
μA7905.2CKC	MC7905.2CT		30
μA7905CKC	MC7905CT		30
μA7905UC	MC7905CT		30
μA7906CKC	MC7906CT		30
μA7906UC	MC7906CT		30
μA7908CKC	MC7908CT		30
μA7912CKC	MC7912CT		30
μA7912UC	MC7912CT		30
μA7915CKC	MC7915CT		30

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
μA7915UC	MC7915CT		30
μA7918CKC	MC7918CT		30
μA7918UC	MC7918CT		30
μA7924CKC	MC7924CT		30
μA7924UC	MC7924CT		30
μA798TC	MC3458P1		22
μA79L05AWC	MC79L05ACP		29
μA79L12AWC	MC79L12ACP		29
μA79L15AWC	MC79L15ACP		29
μA79M05AUC	MC79M05CT		29
μA79M05CKC	MC79M05CT		29
μA79M06AUC		MC79M06CT	29
μA79M06CKC		MC79M06CT	29
μA79M06UC		MC79M06CT	29
μA79M08AUC		MC79M08CT	29
μA79M08CKC		MC79M08CT	29
μA79M08UC		MC79M08CT	29
μA79M12AUC	MC79M12CT		29
μA79M12CKC	MC79M12CT		29
μA79M18AUC		MC79M18CT	29
μA79M18UC		MC79M18CT	29
μA79M24AUC		MC79M24CT	29
μA79M24CKC		MC79M24CT	29
μA79M24UC		MC79M24CT	29
UAA1016B	UAA1016B		72
UC2823DW		MC33023DW	40
UC2823N		MC33023P	40
UC2823Q		MC33023FN	40
UC2825DW		MC33025DW	42
UC2825N		MC33025P	42
UC2825Q		MC33025FN	42
UC2842AD	UC2842AD		39
UC2842AN	UC2842AN		39
UC2842BD	UC2842BD		40
UC2842BN	UC2842BN		40
UC2842D	UC2842AD		39
UC2842N	UC2842AN		39
UC2843AD	UC2843AD		39
UC2843AN	UC2843AN		39
UC2843BD	UC2843BD		40
UC2843BN	UC2843BN		40
UC2843D	UC2843AD		39
UC2843N	UC2843AN		39
UC2844BD	UC2844BD		40
UC2844BN	UC2844BN		40
UC2844D	UC2844D		39
UC2844N	UC2844N		39
UC2845BD	UC2845BD		40
UC2845BN	UC2845BN		40
UC2845D	UC2845D		39
UC2845N	UC2845N		39
UC317T	LM317T		32

= Not recommended for new designs.

Cross Reference (continued)

Industry Part Number	Motorola Nearest Replacement	Motorola Similar Replacement	Page Number
UC337T	LM337T		32
UC3525AN	SG3525AN		42
UC3526N	SG3526N		42
UC3527AN	SG3527AN		42
UC3823DW		MC34023DW	40
UC3823N		MC34023P	40
UC3823Q		MC34023FN	40
UC3825DW		MC34025DW	42
UC3825N		MC34025P	42
UC3825Q		MC34025FN	42
UC3842AD	UC3842AD		39
UC3842AN	UC3842AN		39
UC3842BD	UC3842BD		39
UC3842BN	UC3842BN		39
UC3842D	UC3842AD		39
UC3842N	UC3842AN		39
UC3843AD	UC3843AD		39
UC3843AN	UC3843AN		39
UC3843BD	UC3843BD		40
UC3843BN	UC3843BN		40
UC3843D	UC3843AD		39
UC3843N	UC3843AN		39
UC3844BD	UC3844BD		40
UC3844BN	UC3844BN		40
UC3844D	UC3844D		39
UC3844N	UC3844N		39
UC3845BD	UC3845BD		40
UC3845BN	UC3845BN		40
UC3845D	UC3845D		39
UC3845N	UC3845N		39
UC494ACN		TL594CN	42
UC494CN		TL494CN	42
ULN2003A	MC1413		96
ULN2004A	MC1416		96
ULN2151H	MC1741CP1		21
ULN2151M		MC1741CP1	21
ULN2803A	ULN2803A		96
ULN2804A	ULN2804A		96
ULN8126A	SG3526N		42
ULS2151M		MC1741CP1	21
ULX8161M		MC34060AP	39
UPD6950C		MC10319P	85
UVC3101		MC10319P	85
XR082CP	TL082CP		22
XR084CP	TL084CN		23

= Not recommended for new designs.